



Drobo 5D and Drobo Mini Firmware Release Notes Release Date: June 23, 2015

CONTENTS

VERSION INFORMATION
KEY HIGHLIGHTS
KNOWN ISSUES
RELATED TECHNICAL DOCUMENTATION

VERSION INFORMATION

Drobo Firmware: Version 3.2.1 [7.165.75100]

KEY HIGHLIGHTS

This is a new release of Drobo firmware for Drobo 5D and Drobo Mini.

- Fix USB3 connectivity issues seen primarily on Dell Optiplex i7 host systems

KNOWN ISSUES

General Issues

Symptom: Performance when using a Thunderbolt daisy-chain is slower.

Condition: When a Thunderbolt device is in a daisy-chain with other Thunderbolt devices, the device that's furthest down the chain performs the slowest.

Workaround: Reposition the device you need to behave the fastest to the position in the daisy-chain nearest the computer. Each "hop" in the chain does reduce performance some, but will most likely not affect the majority of uses.

BEST PRACTICES

In accordance with industry best practices, you should always backup your data before any firmware upgrade. For more information, please visit myproducts.drobo.com/support.

Make sure that you keep all software up to date. This includes Drobo Dashboard, which as of this writing the latest release is 2.6.9.

RELATED TECHNICAL DOCUMENTATION

Current Drobo technical reference materials are available on the Drobo Support Website (myproducts.drobo.com/support). This includes:

- *Knowledge Base*
- *Best Practices*
- *Product Documentation*
- *Drobo Help for Mac*
- *Drobo Help for PC*

Copyright 2015 Drobo, Inc. Data Robotics, Drobo, and BeyondRAID are trademarks of Drobo, Inc., which may be registered in some jurisdictions. All other trademarks used are owned by their respective owners. All rights reserved. Specifications subject to change without notice.

P/N 081-00038-001
Rev 01